

# Vol 16 - No 40 ELECTRICAL SHOCK ACCIDENT

#### **INCIDENT DESCRIPTION:**

An apprentice was shocked while hooking up fluorescent lighting. The day before temporary power had been switch to permanent power but this location also had secondary power. The apprentice turned off the main switch but not the emergency power. As he began to connect wires he came in contact with the hot line and was held by the current for several seconds before a co-worker looked up and saw what was happening. He ran over and shut off the secondary power. The worker received severe burns to his hands and a couple of his knuckles had to be surgically repaired. When asked if the apprentice knew about the secondary power and where to shut it off, the supervisor stated that he thought he did.



## SAFETY RECOMMENDATIONS:

Never assume that all workers know what precautions should be taken. Always go over safety precautions and steps to take to assure that all power is off. Lockout-tagout procedures were not used and this crew had not been properly trained.

Location

Date


# Vol 16 - No 40 ELECTRICAL SHOCK ACCIDENT

TOUBOX

### **INCIDENT DESCRIPTION:**

Company

An apprentice was shocked while hooking up fluorescent lighting. The day before temporary power had been switch to permanent power but this location also had secondary power. The apprentice turned off the main switch but not the emergency power. As he began to connect wires he came in contact with the hot line and was held by the current for several seconds before a co-worker looked up and saw what was happening. He ran over and shut off the secondary power. The worker received severe burns to his hands and a couple of his knuckles had to be surgically repaired. When asked if the apprentice knew about the secondary power and where to shut it off, the supervisor stated that he thought he did.



# SAFETY RECOMMENDATIONS:

Never assume that all workers know what precautions should be taken. Always go over safety precautions and steps to take to assure that all power is off. Lockout-tagout procedures were not used and this crew had not been properly trained.