


Vol 16 - No 5 ROLLER MISHAP

Heavy Equipment can be just as dangerous when turned off as it is when work is being performed. The employee operating this roller decided to take a break and parked the roller on what he believed to be a flat surface clear of other vehicles. He pulled the emergency brake, turned off the machine and upon returning to work, started to operate another piece of equipment in a different area of the work site. Thirty minutes later he returned to see the roller had rolled about 30ft and hit the supervisor's truck. Later, after talking to employees, it was discovered that the emergency brake had not been working correctly for about three weeks. This accident could have been worse if it had been parked near vehicular or pedestrian traffic.

Inspections are a must for all equipment on a daily basis. This will ensure that all safety features on equipment will be working properly and those that need attention will be put out of service until repaired. Wheels should be choked or turned away from vehicles or pathways. Simple safety measures can prevent accidents from happening.




A publication of Engineering Safety Consultants, Inc. - P.O. Box 691447 - San Antonio, Texas 78269 - 1-800-327-1516 Visit our website at www.esc-safety.com for a complete list of all our safety services © 2009 - All rights reserved. This publication may not be reproduced in any manner without the written permission of Engineering Safety Consultants, Inc.

TOOLBOX SAFETY Company_____Location______Date_____

Vol 16 - No 5 ROLLER MISHAP

Heavy Equipment can be just as dangerous when turned off as it is when work is being performed. The employee operating this roller decided to take a break and parked the roller on what he believed to be a flat surface clear of other vehicles. He pulled the emergency brake, turned off the machine and upon returning to work, started to operate another piece of equipment in a different area of the work site. Thirty minutes later he returned to see the roller had rolled about 30ft and hit the supervisor's truck. Later, after talking to employees, it was discovered that the emergency brake had not been working correctly for about three weeks. This accident could have been worse if it had been parked near vehicular or pedestrian traffic.

Inspections are a must for all equipment on a daily basis. This will ensure that all safety features on equipment will be working properly and those that need attention will be put out of service until repaired. Wheels should be choked or turned away from vehicles or pathways. Simple safety measures can prevent accidents from happening.



A publication of Engineering Safety Consultants, Inc. - P.O. Box 691447 - San Antonio, Texas 78269 - 1-800-327-1516 Visit our website at www.esc-safety.com for a complete list of all our safety services © 2009 - All rights reserved. This publication may not be reproduced in any manner without the written permission of Engineering Safety Consultants, Inc.