



**Safety Stats
September 2015**

INJURY SAFETY STATS -	Current Month	Year to Date	2014 Year End
Winter Stats:			
First Aid	1	5	5
Medical Only	0	1	6
Days Away Cases (DAW)	0	0	0
Total OSHA Recordables	0	1	6
Recordable Incidence Rate	0	0.37	2.28
Total Winter Hours Worked	37429	537559	526237

Subcontractor Stats:			
First Aid	1	13	5
Medical Only	0	4	5
Days Away Cases (DAW)	0	0	0
Total OSHA Recordables	0	4	5
Recordable Incidence Rate	0	1.03	1.1
Total Subcontractor Hours	82,872	774630	911863
	Estimated	Estimated	

RECORDABLE INJURIES - Month

Winter Injuries:	Supervisor:

Subcontractor Injuries:

FIRST AID INJURIES - Month

Winter:	Supervisor:
Emp stepped off scaffold onto exposed nail puncturing right foot	J Schafer

Subcontractor:

Emp strained right shoulder when catching himself while slipping on excavation spc J Haralson

AUTO ACCIDENTS - YTD


Winter vehicle door struck winter vehicle trailer while leaving parking space	B Mote
Winter Vehicle struck concrete parking obstruction denting quarter panel	D Black
Winter vehicle side swiped by another vehicle	R Flores
Winter vehicle damaged passengar car front bumper while backing up	T Thomas
Winter vehicle struck from behind	J Paulino Capelian
Winter vehicle struck from behind	M Carver

WINTER INCIDENTS - Month

Job	Incident	Supervisor:
15-005	Shoring removed prematurely from area of concrete pour	B Rhoden
14-123	Heavy rains caused small roof leak	J Dye
15-005	7 loads of concrete rejected, replacement not worked	B Rhoden
15-005	Transformer near site was tripped causing power outage	B Rhoden
14-044	3rd party lost her footing at the rolled curb and twisted ankle	G Spears
13-208	Roof sealer leaked down flue duct penetration into unit	B Blauser
14-079	(4) Suites have had storefront glazing crack/shatter	B Gray
14-172	Contractor dug up/broke marked low voltage conduits	G Saborio
15-022	Subcontractor backed backhoe into employee's vehicle	G Spears
13-207	Subcontractor truck struck another vehicle on site	J Schafer
13-208	Temp roofing failed - damage to ceiling and mattress	B Blauser
15-038	Rifle remains dug up by fork lift while moving material	J McFarlin
15-005	Stressed PT cables caused rebar to bend at pour site	B Rhoden

WINTER / SUBCONTRACTOR

**Injuries by Type
Year to Date**



OSHA ACTIVITY - YTD

14-079	Asheville Outlet Mall	Complaint
13-207	NIP	Complaint
15-150, 15-158	Flat Iron	Complaint

SAFETY AUDITS - Month

Date	Job	Score
9/2/2015	15064 - SpringHill Suites Marriott	97
9/2/2015	15047 - NFRMC - 4th Floor East	100
9/9/2015	15038 - Columbus State University	97
9/10/2015	15067 - Harkness Hall 1st Floor R	100
9/11/2015	13208 - NIP Task Order #1	100
9/11/2015	13207 - NIP Task Order #2	100
9/15/2015	14081 - Fulton County Schools Ad	96
9/16/2015	15086 - W&C - ITW Facility, Leeds	100
9/22/2015	15038 - Columbus State University	100
9/24/2015	13207 - NIP Task Order #2	98
9/24/2015	13208 - NIP Task Order #1	100
9/24/2015	15032 - Lockheed B-95 P-3/S-3 Pr	100
9/24/2015	15098 - Lockheed - B-1 Demo Air	100

Milestones - Month