

## Vol 16 - No 44 HEAD INJURY ACCIDENT

INCIDENT DESCRIPTION:

A worker was operating a D8 dozer while other employees were operating scrapers. The dozer operator was helping the scraper operators by pushing their machines when they got stuck. When one of the scrapers was unable to move on an uphill area, he began to push him to loosen him. While pushing the

him. While pushing the scraper, the scraper operator went too fast and got away from the dozer. As a result of this, the front blade of the dozer pushed into the ground causing the dozer to jolt to a stop. This caused the operator to lung forward toward the windshield. By not wearing his seatbelt the operator hit his forehead on an air conditioning box on the ceiling of the cab. He received a head gash approximately one inch long.

## SAFETY RECOMMENDATIONS:

- 1. Always wear your seatbelt while operating any type of machine.
- 2. Have constant contact with the rest of the crew members.



A publication of Engineering Safety Consultants, Inc. - P.O. Box 691447 - San Antonio, Texas 78269 - 1-800-327-1516 Visit our website at www.esc-safety.com for a complete list of all our safety services © 2009 - All rights reserved. This publication may not be reproduced in any manner without the written permission of Engineering Safety Consultants, Inc.



## Vol 16 - No 44 HEAD INJURY ACCIDENT

INCIDENT DESCRIPTION:

A worker was operating a D8 dozer while other employees were operating scrapers. The dozer operator was helping the scraper operators by pushing their machines when they got stuck. When one of the scrapers was unable to move on an uphill area, he began to push him to loosen

him. While pushing the scraper, the scraper operator went too fast and got away from the dozer. As a result of this, the front blade of the dozer pushed into the ground causing the dozer to jolt to a stop. This caused the operator to lung forward toward the windshield. By not wearing his seatbelt the operator hit his forehead on an air conditioning box on the ceiling of the cab. He received a head gash approximately one inch long.

## SAFETY RECOMMENDATIONS:

- 1. Always wear your seatbelt while operating any type of machine.
- 2. Have constant contact with the rest of the crew members.



A publication of Engineering Safety Consultants, Inc. - P.O. Box 691447 - San Antonio, Texas 78269 - 1-800-327-1516 Visit our website at www.esc-safety.com for a complete list of all our safety services © 2009 - All rights reserved. This publication may not be reproduced in any manner without the written permission of Engineering Safety Consultants, Inc.